


STATUS AND RECENT MODIFICATIONS TO 324-MHz RF SOURCE IN J-PARC LINAC

Masato KAWAMURA, Yuji FUKUI, Kenta FUTATSUKAWA, Fujio NAITO, KEK/J-PARC, Ibaraki, JAPAN

Etsuji CHISHIRO, Toshihiko HORI, Fumiaki SATO, Shin-ichi SHINOZAKI, Kazuo HASEGAWA, JAEA/J-PARC, Ibaraki, JAPAN

PRESENT STATUS




Configuration of klystrons and power supply system for klystrons in J-PARC 400MeV linac.

324-MHz Klystron (Toshiba E3740A)

Frequency	324 MHz
Output Power	3 MW
Efficiency	50 %
Gain	55 dB
RF Pulse Length	620 μs
Beam Pulse Length	700 μs
Repetition Rate	50 Hz
Beam Voltage	110 kV
Anode Voltage	94 kV
Beam Perveance	1.37x10 ⁻⁶
No. of cavities	5
Window	Coaxial
Output Flange	WR-2300
Tube Length	4.55 m

High voltage DC power supplies (HVDC01 ~ 05)

No. of klystrons	4
Cathode voltage	110 kV
Average of current	6.3 A
Power	693 kW
Pulse current	180 A
Pulse width	700 μs
Repetition rate	50 pps
Duty factor	5 %
Capacitor bank	25.5 μF



The measured values of the 324-MHz RF source (when the linac accelerate 15mA, 500μs H-beams).

Anode modulators (M1 ~ 20)

(From left to right) DISCON switch, anode-modulator, 324 MHz klystron. The control cabinets are at the right end.

- The linac is upgraded to 400MeV and began to operate on January 17th 2014.
- Since 2006, the majority of the 324-MHz RF source components have total operating times of over 35,000 hours.


RECENT MODIFICATIONS

(1) Recovery from Earthquake Disaster



A large earthquake with a magnitude of 9.0 struck north-eastern Japan on March 11, 2011 (the Great East Japan Earthquake Disaster). The earthquake's intensity at J-PARC measured a "6-lower", which equates to the third highest intensity on the ten-ranked Japanese seismic scale.



Concerning the components of the 324-MHz RF source, the most significant damage was the substantial decrease in the external resistance of the ignitrons. Ignitrons (National Electronics, NL7703EHVNP) are used as crowbar switches, and comprise 29 components of the 6 HVDCs (HVDC1-6). The external resistances between the ignitrons and the cathodes, which are infinite at normal level, decreased by under 10 Ω in 24 components (82.8% overall).



The cause of this decrease was taken to be the shaking sustained in the ignitrons during the earthquake, which resulted in the spillage of the mercury in the ignitrons onto the ignitrons. To repair the 24 faulty ignitrons, the method of impressing DC voltages (2-10 V) between the ignitrons (-) and the cathodes (+) was used. As a result of this treatment, 20 pieces were recovered (a recovery rate of 83.3%). The 4 remaining faulty ignitrons were replaced.



(3) High-voltage Transformers (HVTRs)

A total of 3 HVTRs failed:
 - HVTR01 in Mar. 2012 (the total operating hours was 28,400h (hours)). It was replaced with HVTR11.
 - HVTR02 in Dec. 2013 (30,200h), replaced with HVTR14.
 - HVTR05 in Jun. 2014 (36,000h). It will be replaced with repaired HVTR02.

Diode stacks. Diode module. A breakdown trace in a ceramic condenser (an example). A carbonized ceramic condenser (an example).

(4) Anode-Modulators

Area-1: In the circled area, a lot of discharge occurred. The 10kohm resistor connected lower area.
 Area-2: Sphere electrodes set far from the frame of oil tanks. Transformers dipped in the oil tanks.

The cranes in the linac building could not function, so the anode-modulators were moved overground. (Aug. 2012). Anode-modulators were re-arranged using cranes. (Jul. 2013).