

Vibration Measurements on the MAX-II Beam,
P. RÖJSEL, Max-lab, Lund - Vibration measurements have been done several times during the commissioning period of MAX-II. Almost from the moment of first stored beam until today. Vibrational spectra from a number of these measurements are presented. It is worth noting that the vibration level is generally remarkably low and a the possible reasons for this is discussed.